



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: 24V-256
Safety Advisory: 24-454
April 19, 2024

Recall Population

2024 Sunset Travel Trailers:

Models: **20SS, 253RB, 258RD, 272BH, 330SI**

Serial Number Range:

RS350744 – RS350821

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that the vehicles in the recall population may have a roller shade installed near the stove top instead of a metal mini blind. Under certain conditions while using the stove top, the roller shade can touch the burner leading to an increased risk of fire.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to remove the roller shade and replace it with the correct metal mini blind. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

Please remove the roller shade completely until the corrective measures are implemented. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.nhtsa.gov>.)

